

PURCHASE ORDER Tabaco City LGU

Supplier	B & C EL	ECTRON	<u>MECH</u>	P.O No.:	21-03-0000 20
Address	TABACO	CITY		Date:	MAR 1 n 2021
				Mode of	
				Procurement:	SMALL VALUE
				PR No./s	21-02-0063
Gentleme	n:			22210115	21 02 0000
Please furn	ish this offic	e the follo	wing articles subject to the terms and conditions contained h	nerein:	
Place of De	elivery:	Delivery Term:			
Date of Del	THE RESERVE THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER.	LGU-TA	Payment Term:	3 weeks	
Item No.					Amount (Php)
-				Unit Cost	Amount (Thp)
	J	ob Order	: Repair of CEO Vehicles SJG-763		-
			STC 7/2		
1	1	1-4	SJG-763		-
1	1	lot	JO-Repair & Conditioning	458,500.00	458,500.00
			1. Dismantle/Repair of Main Mast, Cylinder Boom		-
			Rodends, Base Ends and Turn Table Base Extension.		
		 			
			2. Dismantle/Repair of Drive Gear, Pinion Gear at Turn		-
			Table, Mast Boom Hinge Pin and Hydraulic Tank.		
	3. Dismantle/Repair of Inner Mast Boom Hinge F				-
		-	Inner Boom telescopic Extension Rod Packing.		
			4. Dismantle/Repair of Stabilizer Cylinder Rods for		-
			Outrigger Cylinder Sets and Pads Legs Hinge Pin.		
			5. Dismantle/Repair/Cleaning of Hydraulic Main Tank,		-
			Micron Filter, Suction Hose and Fitting Sets.		
			6. Repair of Main Pump Hydraulic System Components		_
			Install New Kitsand Pressure Testing To Standard.		
			7. Repair and Installation of New Sets of Hydraulic Hoses		-
			and Fittings (Crimped Press).		
			8. Repair of Electrical at Swivel (Turn Table) Wiper		_
			Connections, Wiring Replacement and Sockets.		
			9. Dismantle and Repair of Main Control Valve Bank,		_
			Inner Parts O-Rings and Seal Kit Installations		
					_
			10. Installation of Hoses, Proper Positioning, Pressure		
			Relief System Testing and Instrumentation.		
			11. Mast/Boom Pins and Bushing Repair, Grease Fitting		
			and Installation, Center Gear Marking.		
		 	12. Turn Table Installation Backlash Adjustment, lifting	 	
			and Installation of Upper and Lower Boom.		-
		 	13. Installation of Packing at Stabilizer Power Down	 	
			Cylinders and Sleeve and Arm Lubrication.		-
	<u> </u>	 	14. Repair and Installation of Upper Extension Cylinder		
			its end Pins to Extension Boom Assembly.		-
		1	15. Repair of Boom Swing Counter Balance Valve and	 	-
			Brake Removal/Installation of Mounting Bolts.		
		+	16. Main Pump to Switch Bracket Repair, Gasket Leak	-	
			Repair and Loose Mounting Bolt Replacement.		-
	1		17. Dismantle and Repair of Front and Rear Wheels	-	
			Bearings Brake System and Grease Lubrication.		-
		 		-	
			18. Body Dents Repair, Bumper, Windows Brackets and		-
		+	Sidding Metal Welding and Repair Hinges.		
			19. Electrical Wiring Repair, Headlight, Signal Light,		-
		1	Clearance Light, Switches and Relay.	-	
			20. Engine Change Oil, Change Fuel Filter, Fan belts,		-
	-	+	Alternator and Starter Conditioning.	-	
×			21. Seat Cover Uphostery, Side Mirrors Installation and		-
		+	Brackets Repair and Sliding Glass Window.	-	
			22. Fuel Tank Dismantle, Sludge Cleaning and Fuel		-
	-	-	Transparent Nylon Hose and Clamp Replacement.		
		-	***nothing follows***		-
				TOTAL	458,500.00
			Four Hundred Fifty-Eight Thousand Five Hundred P	esos	



PURCHASE ORDER

Tabaco City LGU

						. 1				
Supplier	B & C ELECTRON	IECH		P.O No.:	21-03-0070					
Address	TABACO CITY				Date:	MAR 1 0 2021				
					Mode of	CREATE VIATER				
					Procurement:	SMALL VALUE				
				/	PR No./s	21-02-0063				
In case of failure to make the full delivery within the time specified above, a penalty of one-tenth (1/10) of one percent for every										
day of delay shall be imposed										
CONFOR	RME:	Very Truly yours,		4/						
Se-										
\$ 5	Brun	CIELO KRISEL LAGMAN-LUISTRO								
(Signature	over printed name)	City Mayor								
(Date)										
(In case of Negotiated Purchase pursuant to section 369 (a) of RA 7160, this portion must be accomplished.)										
Approved per Sangguniang Resolution No.:										
		Date:								
Certified C	orrect:		-							

DATE RECEIVED: 8 22 MILES PINES

DESCRIPTION OF TABACO

DATE RECEIVED: 8 22 MILES PINES

DATE RECEIVED: 10:32 m