



# PURCHASE ORDER

Tabaco City  
LGU

Supplier	<b>B &amp; C ELECTROMECH</b>	P.O No.:	<u>20-0774</u>
Address	<b>TABACO CITY</b>	Date:	<u>10/09/2020</u>
		Mode of Procurement:	<b>SMALL VALUE</b>
		PR No./s	<b>20-09-1278</b>

Gentlemen:

Please furnish this office the following articles subject to the terms and conditions contained herein:

Place of Delivery:	LGU-TABACO CITY - GENERAL SERVICES OFFICE	Delivery Term:	
Date of Delivery:		Payment Term:	3 weeks

Item No.	Qty	Unit	DESCRIPTION	Unit Cost	Amount (Php)
<b>Vehicle Repair &amp; Maintenance of Meat Van with Conduction Sticker KOA-550 of City Abattoir</b>					
1	1	lot	JO-Labor & Materials	91,500.00	91,500.00
			A. Hyundai Truck 1 Ton Capacity Hydraulic Lifter Mechanical and Electrical Repair		-
			1. Welding and cutting of lifter rear chassis mounting bracket, bolts and wiring connections removal		-
			2. Dismantling and lifting of hydraulic mechanism, boom support and load platform lift arms		-
			3. Dismantling of hydraulic hoses and installation of new sets of 2 wire high pressure hoses		-
			4. Dismantling of hydraulic parts at mounting, check valve, blocks and high pressure pump unit		-
			5. Hydraulic oil draining, cleaning and lifting of O-rings and seals and re-assembly		-
			6. Reinstallation of hydraulic parts, fittings and refill of hydraulic oil		-
			7. Lifting and reinstallation of hydraulic mechanism to truck chassis bolting and welding brackets		-
			8. Reinstallation of electrical wirings (Hydraulic side) remote connection and power source		-
			9. Pressure test, de-aeration of system and run test		-
			10. Repair and repainting of loading tube corroded ramp		-
			B. Aircon Repair and Conditioning		-
			1. Dismantling of A/C compressor and perform leak and pressure test		-
			2. Dismantling of condenser and front blower and evaporator and perform leak and pressure test		-
			3. Replacing deffetive hoses and fittings with leakages and reinstall dismantled parts and leaktest again		-
			4. Load freon, install new belts and run test aircon		-
			C. Installing front and rear camera at front cab and rear loading cabin		-
			D. electrical repair-cigarette igniter, signal lights and readjust of brake linings		-
			E. Drain and change oil, oil filter, fuel filter and change fan belts		-
			***nothing follows***		-
<b>TOTAL</b>					<b>91,500.00</b>

**Ninety-One Thousand Five Hundred Pesos**

In case of failure to make the full delivery within the time specified above, a penalty of one-tenth (1/10) of one percent for every day of delay shall be imposed

CONFORME: Very Truly yours,

REPUBLIC OF THE PHILIPPINES  
 OFFICE OF THE CITY AUDITOR  
 CITY OF TABACO  
 DATE RECEIVED: 12/2/20  
 RECEIVED BY: [Signature]  
 TIME RECEIVED: 10:08 am

In case of failure to make the full delivery within the time specified above, a penalty of one-tenth (1/10) of one percent for every day of delay shall be imposed

CONFORME: Very Truly yours,

(Signature over printed name)  
 (Date)

**CIELO KRISSEL LAGMAN-LUISTRO**  
 City Mayor

(In case of Negotiated Purchase pursuant to section 369 (a) of RA 7160, this portion must be accomplished.)

Approved per Sangguniang Resolution No.:

Date:

Certified Correct:

Secretary to the Sanggunian